

(JA/97)

Information for Harrow Re: Structure

Tina Donoghue

From: Allen, John: CP-Plan: RBKC
Sent: 18 June 2017 10:59
To: martin.tucker@met.pnn.police.uk
Subject: FW: walls

For hbc

John Allen
Building Control Manager
The Royal Borough of Kensington and Chelsea
The Town Hall, Hornton Street, London W8 7NX
Tel: [REDACTED] | Mob: [REDACTED]
Email: john.allen@rbkc.gov.uk | Website: www.rbkc.gov.uk

From: Barbara Lane [mailto:Barbara.Lane@arup.com]
Sent: 14 June 2017 16:17
To: Allen, John: CP-Plan: RBKC <John.Allen@rbkc.gov.uk>
Cc: CHARLES.ROMEYER@london-fire.gov.uk
Subject: walls

No reply required.

Are they insitu or precast?


Have they moved significantly?

Risk then becomes buckling, particularly if slab can no longer restrain the walls.

If they are loadbearing this is a concern.

Barbara

Dr Barbara Lane FREng CEng



Technology Group leader UKMEA Board

Arup
15 Fitzroy Street
London W1T 4BQ
d [REDACTED]
m [REDACTED]
www.arup.com

Electronic mail messages entering and leaving Arup business systems are scanned for viruses and acceptability of content